




Assembly Instructions for 408116 Steel Drying Rack




A




x 4

B



x 80

C



x 20

D



x 40

E



x 20


F




Lock Nuts require extra force to screw in place.

x 20

G



x 1




Screwdriver needed (not included).

Assembly Instructions for 408116 Steel Drying Rack




STEP 1




Use wrench (G) to hold lock nut (F) while turning screwdriver.

STEP 2




STEP 3



Shelves ③ need to be attached to Frame ① starting at the bottom and working up.

Apply Rubber Bumpers (B) to Shelf (3) on outside edges (as shown).

STEP 4



Bumpers need to be aligned so they are supporting each rack.